


STAND PARTS LIST & DRAWINGS3.vsd



NOTE: 2 OF EACH REQUIRED PER FRAME
 DOTTED LINES DENOTE ANGLE CUTS



Gery Stocker